

25828

REPORT of SURVEY for REPAIRS.

No. 3 Survey held at London Date 18th Nov^r 1863
 on the S. Vernon Master Jones
 Tonnage 911 Built at London When built 1839
 By whom built _____ Owners Powell & Co
 Port belonging to London Destined Voyage Queensland
 If Surveyed Afloat or in Dry Dock Green's lower Dock & E. S. Dock

Last Survey, No. 24978Port LondonClassed C 4 A 1 Red
33. 57. 8 yrs.

REPAIRS

Yellow metal stripped caulked keel to middle
 line of deck and the yellow metal renewed
 on Felt

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>Good &</u>
Lower Deck Beams & Fastenings <u>Good</u>	Ditto Ditto at other places <u>Good</u>	Sails
Planksheers <u>where</u>	Keelsons <u>where</u>	Anchors No. of <u>sufficient</u>
Sheerstrakes <u>seen</u>	Clamps and Shelves <u>seen</u>	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>T. & M.</u> When put on <u>now</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where tested</u>	

This vessel appears in good condition "fit for the conveyance
 of dry and perishable cargoes to and from all parts of the world"
 and is eligible in my opinion to remain as classed

The Amount of Fee.....£ 1 is received by me,Special..... 1: 1: 1Certificate (if required) : 5Committee's Minute 27th November 18 63Character assigned A 1 in Red

© 2021

Lloyd's Register
Foundation

408647-0484