

# REPORT of SURVEY for REPAIRS.

25968

Recd. 16.1.64

No.                      Survey held at London Date Jan 4<sup>th</sup> 1864  
 on the Ship "Labelia" Master Soblin  
 Tonnage 540 Built at Sunderland When built 1833  
 By whom built                      Owners S. Lidgate  
 Port belonging to London Destined Voyage                       
 If Surveyed Afloat or in Dry Dock Shops' Youngs' Dry Dock -

st Survey, No. 17109 Port Liverpool. Classed 13 A. 1

REPAIRS

*Now done, her bottom and the butto of her topsides  
 Caulked, and her bottom sheathed with Yellow  
 Metal on Tell in the upper Course, from thence  
 to the Keel on Paper.*

## Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	} <i>Good where seen</i>	Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} <i>Good</i>	Timbers of the Frame at the openings		Masts, Yards, &c.	} <i>Good and sufficient</i>
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Sails	
Planksheers	} <i>Butts Caulked</i>	Keelsons	} <i>Good where seen</i>	Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter	<i>Caulked</i>	<i>Yellow Metal</i> <i>Copper on Tell - When put on</i>	<i>how</i>		

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. *Good where tested.*  
*She is now in good and efficient condition, fit  
 in my opinion to remain as classed 13 A. 1.*  
*B. W. Maymouth*

The Amount of Fee.....£            is received by me,  
 Special..... 1 : 1 : - *MB*

Certificate (if required)           

Committee's Minute 12<sup>th</sup> February 1864

Character assigned 13 A. 1  
*second MB*



© 2019  
 Lloyd's Register  
 Foundation  
 LVN 648 - 0088