

25072

Change of Owners
REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 380 Survey held at London Date Jan^y to Mar^y 14th 1864
on the Barque "Great Britain" Master R. Byford
Tonnage 532 NA Built at Sunderland When built 1834
By whom built _____ Owners G. C. Schutz &
Port belonging to London Destined Voyage Narrackee
If Surveyed Afloat or in Dry Dock On Ashore Dry Dock & West India Dock

Last Survey, No. 24498 Port London Classed 10 A. 1.
62

REPAIRS

Now done, the main piece of Rudder renewed with English Oak. The Ice chocks taken off from her bows and dispensed with. The bottom Caulked where throes exposed and sheathed with Yellow Metal on Telt. - Caulked from the Yellow Metal sheathing to the centre of the upper deck. two planks of upper deck renewed.

Present Condition of the

Decks <u>Caulked</u>	Treenails _____	Windlass and Capstan _____
Waterways <u>Caulked</u>	Breasthooks and Stemson _____	Pumps _____
Comings <u>Good</u>	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings } <u>Good</u>	Timbers of the Frame at the openings _____	Masts, Yards, &c. } <u>Good and</u>
Lower Deck Beams & Fastenings } <u>Good</u>	Ditto Ditto at other places _____	Sails } <u>Sufficient</u>
Planksheers _____	Keelsons } <u>Good where</u>	Anchors No. of _____
Sheerstrakes } <u>Caulked</u>	Clamps and Shelves } <u>Seen</u>	Cables _____
Topsides } <u>Caulked</u>	Ceiling _____	Hawsers and Warps _____
Wales _____	Rudder <u>Yellow Metal</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	Copper _____ When put on <u>1862</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

She is now in good condition, fit in my opinion to remain as classed 10 A. 1. until the end of this year -

B. W. Wainwright

The Amount of Fee.....£ / : - is received by me,

Special..... / : / : -

Certificate (if required) - : -

Committee's Minute 8th April 18 64

Character assigned 11/12



© 2019

Lloyd's Register
Foundation

LN 648-0180