

26187

REPORT of SURVEY for REPAIRS.

No. 130 on the Ship "Lansdowne" Master Spowart
Survey held at London Date May 25th to 27th 1864
Tonnage 715 Built at Workington When built 1856
By whom built Owners Vickerman
Port belonging to London Destined Voyage New Zealand
If Surveyed Afloat or in Dry Dock Young's Dry Dock

Last Survey, No. 24793 Port Londn. Classed 10 A. 1
62

REPAIRS

Now don the Yellow Metal sheathing stripped off
and the Bottom faulted and resheathed with
Yellow Metal on felt

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	} good	Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches	good	Boats	} good
Upper Deck Beams & Fastenings	} firm	Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places	where	Sails	} and
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes	} good	Clamps and Shelves	seen	Cables	} sufficient
Topsides		Ceiling		Hawsers and Warps	
Wales	} seen	Rudder		Standing & Running Rigging	}
Plank (Bottom) and Counter		Copper & Man felt When put on	now		

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where tested

She is now in good condition, fit in my opinion
for the safe conveyance of dry cargoes to and from
all parts of the World and to remain as classed 10 A. 1

The Amount of Fee.....£ : : is received by me,
Special..... 1 : 1 : -

Hornish

Certificate (if required) : : :

Committee's Minute 14th June 1864

Character assigned 10 A. 1 record
Charge £ 1-1