

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 22 Survey held at London Date Feb. 20th 18 65
 on the S "York" Master Brearey
 Tonnage 865 Built at Sunderland When built 1854
 By whom built 940 Owners J. H. Allan
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock in Fletcher's & East India Docks

Last Survey, No. 25870 Port London Classed 13 A1
10-63

REPAIRS

Stripped Yellow metal sheathing, caulked from keel to Planksheer and re-sheathed with Yellow metal over felt.

Present Condition of the

Decks <u>where seen</u> <u>Good</u>	Treenails <u>where seen</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u> <u>"</u> <u>"</u>	Breasthooks and Stemson <u>"</u> <u>"</u> <u>"</u>	Pumps <u>"</u> <u>"</u> <u>"</u>
Comings <u>"</u> <u>"</u> <u>"</u>	Transoms, Pointers, and Crutches <u>"</u> <u>"</u> <u>"</u>	Boats <u>"</u> <u>"</u> <u>"</u>
Upper Deck Beams & Fastenings <u>"</u> <u>"</u> <u>"</u>	Timbers of the Frame at the openings <u>"</u> <u>"</u> <u>"</u>	Masts, Yards, &c. <u>"</u> <u>"</u> <u>"</u>
Lower Deck Beams & Fastenings <u>"</u> <u>"</u> <u>"</u>	Ditto Ditto at other places <u>"</u> <u>"</u> <u>"</u>	Sails <u>"</u> <u>"</u> <u>"</u>
Planksheers <u>"</u> <u>"</u> <u>"</u>	Keelsons <u>not seen</u>	Anchors No. of <u>1 B, 1 S, 2 K</u>
Sheerstrakes <u>"</u> <u>"</u> <u>"</u>	Clamps and Shelves <u>"</u> <u>"</u> <u>"</u>	Cables <u>"</u> <u>"</u> <u>"</u>
Topsides <u>"</u> <u>"</u> <u>"</u>	Ceiling <u>"</u> <u>"</u> <u>"</u>	Hawsers and Warps <u>"</u> <u>"</u> <u>"</u>
Wales <u>"</u> <u>"</u> <u>"</u>	Rudder <u>"</u> <u>"</u> <u>"</u>	Standing & Running Rigging <u>"</u> <u>"</u> <u>"</u>
Plank (Bottom) and Counter <u>"</u> <u>"</u> <u>"</u>	Copper <u>F.Y.M.</u> When put on <u>1865</u>	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. where tested Good

Do now in good and efficient condition and is in my opinion fit to remain as classed

The Amount of Fee.....£ is received by me, John Maxwell

Special..... 1 : 1 : 0

Certificate (if required)

Committee's Minute 10th March 18 65

Character assigned 13 A1
second 4M