

REPORT of SURVEY for REPAIRS.

26975

No. in Reg. Book. **No.** 249 Survey held at London Date 14th to 17th Aug^r 1865.
 on the Barge "Hoping Fish" Master J. D. Taylor.
 Tonnage 393 Built at Sunderland When built 1858.
 By whom built _____ Owners Javan. B.
 Port belonging to London Destined Voyage West Indies.
 If Surveyed Afloat or in Dry Dock Tommy's Dry Dock.

Last Survey, No. 26277 Port London. Classed 13. A. I.
 64

REPAIRS

Now done:-

The copper-sheathing stripped off the Bottom and caulked from keel to metal line..
 Resheathed the Bottom with copper or felt..

Present Condition of the

Decks	Treenails	Windlass and Capstan	
Waterways	Breasthooks and Stemson	Pumps	Good
Comings	Transoms, Pointers, and Crutches	Boats	and
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. By inquiry of Condition, how ascertained.	Sufficient
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails	where
Plank-sheers	Keelsons	Anchors No. of	
Sheerstrakes	Clamps and Shelves	Cables	seen.
Topsides	Ceiling	Hawsers and Warps	
Wales	Rudder	Standing & Running Rigging	
Plank (Bottom) and Counter	Copper on felt When put on		Good where tested..
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.		

She is now in good and efficient condition, and fit, in our opinion, to remain as classed:- 13. A. I.

The Amount of Fee.....£ _____ is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : 3 : -

Committee's Minute 1st September 18 65.

Character assigned 13 A. I.

record copper



© 2021

Lloyd's Register Foundation

LON 650-0073