

# REPORT of SURVEY for REPAIRS.

27085

121 No. Survey held at London Date Sept<sup>r</sup> 14<sup>th</sup> 1865  
 on the S. "Newcastle" Master Saylor  
 Tonnage 1137 Built at Sunderland When built 1859  
 By whom built \_\_\_\_\_ Owners Green  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Greens lower dock & E. S. Dock

Last Survey, No. 24697 Port London Classified 13 A 1  
 62

## REPAIRS

In consequence of damage, see Special Report;  
 the main piece of Rudder renewed and the  
 cutwater repaired.

One bow Anchor has been supplied at  
 Calcutta see owners letter, and the following  
 chains here viz. <sup>each</sup>  
 76 fathoms of  $1\frac{3}{4}$  Proved at Sloyds to 55  $\frac{7}{10}$  Tons  
 15- "  $1\frac{13}{16}$  " " 59  $\frac{7}{10}$  "

## Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. <u>Good and</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons <u>where seen</u>	Sails <u>sufficient</u>
Planksheers <u>where seen</u>	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder <u>new</u>	Hawsers and Warps
Wales	Copper <u>F. &amp; M.</u> When put on <u>Nov 1861</u>	Standing & Running Riggng
Plank (Bottom) and Counter	Caulking of Bottom, Deck, & Waterways. <u>where tested good</u>	
General Observations and Opinion,		

This vessel is now good condition and is  
 eligible in my opinion to remain  
 classed

The Amount of Fee.....£ 3 : - : - is received by me,

Special..... 3 : 3 : -  
 Certificate (if required) : 5 : -

Committee's Minute 10<sup>th</sup> November 18 65

Character assigned 13 A 1

record damage repair  
 MIT



© 2021

Lloyd's Register  
 Foundation

LON 650-072