

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 64 Survey held at London Date Nov. 1st 6th 1865.
 on the Ship Lady Macdonald Master J. Mather.
 Tonnage 678 Built at Moulmain When built 1847.
 By whom built — Owners G. Duncan.
 Port belonging to London Destined Voyage Calcutta.
 If Surveyed Afloat or in Dry Dock "Lavender"

Last Survey, No. 26312 Port Londond Classed Constⁿ/59. 8. A. 1.
 64

REPAIRS

Stripped off the Yellow Metal Sheathing
 Caulked the doubling planks, and resheathed
 with yellow metal on felt up to 18 feet

Present Condition of the

Decks <u>in good order</u>	Treenails <u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>from the Deck</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Anchors No. of <u>2</u> <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Rudder <u>efficient</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>Yellow Metal</u> When put on <u>now</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good</u>	

I am of opinion she is entitled to remain
 as Class'd Constⁿ/59-8. A. 1.

Samuel Pascoe

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : -

Certificate (if required) : 5 : -

Committee's Minute 1st December 1865

Character assigned Constⁿ 8 A 1
record YM
mt



© 2021

Lloyd's Register
 Foundation

LON 650-0204

Lady MacDonald ✓



© 2021

Lloyd's Register
Foundation