

REPORT of SURVEY for REPAIRS.

27448

13/12/65

No. in Reg. Book. **No.** 6 Survey held at London. Date 10th Nov. to 9th Dec. 1865.
 on the B^{ty} "Alice Burnyeat" Master Richard Kore.
 Tonnage 199 Built at P.E. Islands. When built 1865.
 By whom built Langworth Owners Andrews
 Port belonging to London. Destined Voyage River Plate.
 If Surveyed Afloat or in Dry Dock Duke Shore Dry Dock and S^t Katharine's Dock.

Last Survey, No. 26881 Port London. Classed J. A. 1
AVC 7.65.

REPAIRS Now done:- Caulked from the keel to the Brads, and sheathed the Bottom with Yellow Metal on felt, up to 10 feet aft, and 9.6" forward. Renewed a stake of deck next the Waterway on the Port side with yellow Rail.

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	} fine	Breasthooks and Stemson	} good	Pumps	} good
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings	} where	Timbers of the Frame at the openings	} where	Masts, Yards, &c.	} and
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <i>By inquiry & observation from the deck.</i>	
Planksheers		Keelsons		Sails	
Sheerstrakes	} seen.	Clamps and Shelves	} seen.	Anchors No. of	} sufficient
Topsides		Ceiling		Cables	
Wales	} Caulked part.	Rudder	} now	Hawsers and Warps	}
Plank (<u>Bottom</u>) and Counter		Copper F.Y.M. When put on		Standing & Running Rigging	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <i>good where tested.</i>			

She is now in good and efficient condition, and fit, in our opinion, to remain as classed:- viz. J. A. 1.

The Amount of Fee.....£..... is received by me,
 Special..... 1 : 1 :
 Certificate (if required) : 2 : 6

Committee's Minute 15th May 1866
 Character assigned 7th record

W. Williamson.