

REPORT of SURVEY for REPAIRS.

27641

No. in Reg. Book. **No.** 1103 on the BK "Avery" Survey held at London Date August 1st 18 66
 Tonnage 380 Built at Shaldon Master John H. Place When built 1855
 By whom built Owners Avery & Co
 Port belonging to Dartmouth Destined Voyage
 If Surveyed Afloat or in Dry Dock in Ratcliffe loss dry & West India Dock
 Last Survey, No. 25734 Port London Classed 12 A1
 J. 63

REPAIRS

This vessel was placed in dry dock as it was said for the purpose of stripping the yellow metal sheathing, caulking bottom &c; she remained there several days without anything having been done to her (the reason given being that no instructions had been received from the Owner) although her sheer was much broken, the upperworks appeared strained and the metal sheathing was much wrinkled; she was ultimately very unexpectedly undocked and taken to the West India Dock. — Understanding that the vessel was for sale I communicated by letter with the Owner, a copy of which I append, and have since received a reply from his agents a copy of which I also append.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>F.Y.M.</u> When put on <u>1863</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

Having submitted the above I beg respectfully to leave the character of this vessel in the hands of the Committee.

The Amount of Fee.....£..... is received by me, John Maxwell

Special.....:.....

Certificate (if required) : :

Committee's Minute 10th August 18 66
September 1866

Character assigned

Repaired
Notice to Owner
Letter 14.9.66



Referred
 made over
 10/8/66
 Lloyd's Register
 Foundation

LOW 651-0094