

27653

Damage Repair, -
REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** Survey held at London. Date 18th July to 4th Augst 18 66.
477 on the Ship "Silver Eagle" Master John Ross.
Tonnage 903 Built at Troon When built 1861 (S. No.)
By whom built Orkland S. S. Owners Merchant Shipping Co. Ltd.
Port belonging to London. Destined Voyage Shanghai.
If Surveyed Afloat or in Dry Dock final Dry Dock and East India Dock.

Last Survey, No. 27106 Port Lon. Classed 13. A. 1.
10. 65.

REPAIRS Now done:- Bottom sighted and the Yellow Metal patched. Caulked the upper deck, and renewed the Mizzen-mast with Yellow-pine.

Now done to make good damage:- Repaired the Knee-of-Head, and caulked the fore-hoods-ends from the 15 feet Water-mark upwards

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	caulked.	Breasthooks and Stemson		Pumps	Two
Comings	good	Transoms, Pointers, and Crutches	good	Boats	Five
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	See Mizzen-mast
Lower Deck Beams & Fastenings	where	Ditto Ditto at other places	where	Condition, how ascertained	By inquiry & observation
Planksheers		Keelsons		Sails	good and
Sheerstrakes		Clamps and Shelves		Anchors	No. of 3 B. 15. 2 R.
Topsides		Ceiling	seen.	Cables	sufficient
Wales	seen.	Rudder		Hawsers and Warps	where seen.
Plank (Bottom) and Counter		Copper <u>As before</u> When put on <u>1865</u>		Standing & Running Rigging	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.	good where seen.		

She is now in good and efficient condition, and fit, in our opinion, to remain as classed:- 13. A. 1.

The Amount of Fee.....£..... is received by me,

Special.....

Certificate (if required).....

Committee's Minute 17th August 18 66.

Character assigned 13 A 1

Special charge for damage survey £1.1.0

Williamson.
J. Allen.

