

Composite Ship Change of Owners - REPORT of SURVEY for REPAIRS.

27963

No. in Reg. Book. **No.** 450 Survey held at London Date Dec^r 13^d 1866
on the Ship "John R Worcester" Master R. S. Wawn
Tonnage 844 Built at Port Glasgow When built 1865 (11 mo.)
By whom built _____ Owners John Patton jun
Port belonging to London Destined Voyage Shanghai
If Surveyed Afloat or in Dry Dock Thames Dry Dock

Last Survey, No. 5015 Port Greenock Classed 12 A.1.
Iron Frame planked E/p. B. 1. 66.

REPAIRS now done.

The bottom sighted and the
Yellow Metal patched -

Present Condition of the

Decks	} <u>good</u>	Treenails	} <u>good</u>	Windlass and Capstan	} <u>good</u>	
Waterways		Breasthooks and Stemson		Pumps		
Comings		Transoms, Pointers, and Crutches		Boats		<u>five</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.		<u>where</u>
Lower Deck Beams & Fastenings	} <u>where</u>	Ditto Ditto at other places	} <u>where</u>	Condition, how ascertained	<u>from the deck</u>	
Planksheers		Keelsons		Sails	<u>two suits</u>	
Sheerstrakes		Clamps and Shelves		Anchors	No. of <u>3 B 1 S 2 K</u>	
Topsides		Ceiling		Cables	<u>seen</u>	
Wales	} <u>seen</u>	Rudder	} <u>seen</u>	Hawsers and Warps		
Plank (Bottom) and Counter		Copper <u>ST. Y. M.</u> When put on <u>66 GIB</u>		Standing & Running Rigging		
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.	<u>good where seen</u>			

She is now where seen in good condition,
fit in my opinion to remain as classed 12 A.1.

The Amount of Fee.....£ 1 : : is received by me.


Special.....

Certificate (if required) : 5 :

Committee's Minute 27th December 1866

Character assigned 12 A.1

Change of Owner fee £1.



© 2019

Lloyd's Register
Foundation

LOW 651-0348