

See Reports annexed. 27967
REPORT of SURVEY for REPAIRS. Rec 24/8/66

No. in Reg. Book, **No.** 113 Survey held at London Date 25th July to 10th Augth 1866.
 on the Ship "Essex" Master J. Attwood.
 Tonnage 1042 Built at London When built 1862 (Y. No. 1)
 By whom built Nigraun Owners Nigraun & Sons.
 Port belonging to London Destined Voyage Australia.
 If Surveyed Afloat or in Dry Dock Blackwall Dry Dock and East India Dock.
 Last Survey, No. 27967 Port London Classed 13.A.1.6.63.
See annexed Reports.

REPAIRS
 Yellow Metal sheathing stripped, and the Bottom and upper deck caulked. The Bottom resheathed with Yellow Metal over felt.

Present Condition of the

Decks	} Caulked. } Good	Treenails	} Good	Windlass and Capstan	} Good
Waterways		Breasthooks and Stemson		Pumps	
Comings	} where	Transoms, Pointers, and Crutches	} where	Boats	} and
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	} seen.	Ditto Ditto at other places	} seen.	Condition, how ascertained	} sufficient
Planksheers		Keelsons		Sails	
Sheerstrakes	} Caulked	Clamps and Shelves	} Good	Anchors No. of	} where
Lopsides		Ceiling		Cables	
Wales	} Caulked	Rudder	} Good	Hawsers and Warps	} seen.
Plank (Bottom) and Counter		Copper		Standing & Running Rigging	


General Observations and Opinion, Caulking of Bottom, Deck, & Waterways, Good where tested.

She is now in good and efficient condition and fit, in our opinion, to remain as classed.

The Amount of Fee.....£ : : is received by me,
 Special..... 1 : 1 :
 Certificate (if required)..... : :
W. H. Keen

Committee's Minute 28th December 1866

Character assigned 13.A.1 record *W. H. Keen*



© 2019

Lloyd's Register Foundation

LOV 651 -0352