

28245

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 986 Survey held at London Date Nov^r 29th 18 66
 on the S "Foulmakyfe" Master A. Morison
 Tonnage 579 Built at Aberdeen When built 1862
 By whom built Hall Owners J. Jameson
 Port belonging to Liverpool ~~Aberdeen~~ Destined Voyage Shanghai
 If Surveyed Afloat or in Dry Dock in Ratcliff Cross & West India Dock

Last Survey, No. 2070 Port Aberdeen Classed 13.41
8.62

REPAIRS

Stripped Yellow metal sheathing, caulked from Keel to metal line
 and re-sheathed with Yellow metal over part felt

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways " " "	Breasthooks and Stemson " " "	Pumps " "
Comings " " "	Transoms, Pointers, and Crutches " " "	Boats " "
Upper Deck Beams & Fastenings " " "	Timbers of the Frame at the openings " " "	Masts, Yards, &c. " "
Lower Deck Beams & Fastenings " " "	Ditto Ditto at other places " " "	Condition, how ascertained <u>from enquiry & as seen from deck</u>
Planksheers " " "	Keelsons " " "	Sails " "
Sheerstrakes " " "	Clamps and Shelves " " "	Anchors No. of <u>3 B, 1 S, 2 K</u>
Topsides " " "	Ceiling " " "	Cables " "
Wales " " "	Rudder " " "	Hawsers and Warps " "
Plank (Bottom) and Counter " " "	Copper <u>Pt F, YM</u> When put on <u>1866</u>	Standing & Running Rigging " "
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where tested Good</u>	

Is now in good and efficient condition and is in my opinion fit to remain as classed

The Amount of Fee.....£ is received by me, John Maxwell

Special..... 1 : 1 : 0

Certificate (if required) : 5 :

Committee's Minute 7th May 18 66

Character assigned 13A



© 2021

Lloyd's Register
Foundation

LON652-0019

London
date



© 2021

Lloyd's Register
Foundation