

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 337 Survey held at London Date May 7<sup>th</sup> 18 67  
 on the Bk Point Master Millard  
 Tonnage 311 Built at London When built 1848  
 By whom built Fletcher & Co Owners Anderson Thomson & Co  
 Port belonging to \_\_\_\_\_ Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock in Union and Nelson Docks

Last Survey, No. 27872 Port London Classed 13 A1  
 Cont 61. 9 10.66

## REPAIRS

Stripped three upper courses of Yellow metal sheathing, caulked seams of planking where stripped and re-sheathed two courses of Yellow metal over felt.

This vessel was re-docked for the purpose of discovering a leak which existed and which was found to proceed from some small holes in a plank over which a piece was placed also from the scarp of stem; both of these defects have now been remedied.

### Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto Ditto at other places _____	Condition, how ascertained <u>from enquiry &amp; as seen from dock</u>
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors No. of <u>3 B, 1 S, 1 K</u>
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper <u>F.Y.M.</u> When put on <u>1866</u>	Standing & Running Rigging _____
General Observations and Opinion, _____	Caulking of Bottom, Deck, & Waterways. <u>where seen Good</u>	

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£ — : — : — is received by me,

Special..... 1 : 1 : 0 3

Certificate (if required) : :

Committee's Minute 17 May 18 67

Character assigned Contg 1 MASS.



© 2021

Lloyd's Register Foundation

Lon652-0040



REPORT OF THE  
COMMISSIONERS OF THE  
LAND OFFICE

1894

