

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 237 Survey held at London Date July 16th to 29th 1867
 on the Ship Peterborough Master B. Orchard
 Tonnage 560 Built at Sunderland When built 1859
 By whom built Austin Owners Stanley
 Port belonging to London Destined Voyage Shanghai
 If Surveyed Afloat or in Dry Dock Limetree (Dry Dock)

Last Survey, No. 27974 Port Lon. Classed B A 1.
 REPAIRS how done,

The yellow metal stripped, caulked from the keel to the middle line of upper deck, and the bottom resheathed with yellow metal upon felt —

Present Condition of the

Decks <u>caulked</u>	Treenails	Windlass and Capstan
Waterways <u>dr</u>	Breasthooks and Stemson	Pumps
Comings <u>dr</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers <u>caulked</u>	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter <u>caulked</u>	Copper <u>T'k YN</u> When put on <u>now</u>	Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now in good condition, fit in our opinion to remain as classed B A 1.

The Amount of Fee.....£ — : — : is received by me,
 Testing Caulking 1 : 1 :
 Special.....

Certificate (if required) : :

Committee's Minute 2nd August 18 67

Character assigned 13 A 1

LON652-0199



© 2021

Lloyd's Register Foundation