

28563

Rev 2/9/67

(Annual)
REPORT of SURVEY for REPAIRS.

No. 1 Survey held at London Date Augth 2nd to 30th 1867
on the Ship "Lady Melville" Master W Styles
Tonnage 966 Built at Sunderland When built 1859
By whom built Haswell Owners Green and Co
Port belonging to London Destined Voyage Melbourne
If Surveyed Afloat or in Dry Dock Green's Up^r dry Dock and East India St^s

Last Survey, No. 27760 Port London Classed B.A.1 (9.66.)

REPAIRS Now done.

Sighted bottom the yellow metal patched; limber boards lifted from main hatch forward to about 70 feet; the fore peak, and rings, much lumbered with ballast &c.

Caulked the butts &c of topsides, the whole of upper deck, and part of Lower deck,

Renewed the bowsprit and mizen topmast with Red pine, also the Fore, main and mizen topsail yards, and the main yard, with Red pine and Battic spars.

Present Condition of the

Decks	<p><i>Good</i></p> <p><i>where</i></p> <p><i>seen</i></p>	Treenails	<p><i>Good</i></p> <p><i>where</i></p> <p><i>seen</i></p>	Windlass and Capstan	<p><i>Good and efficient</i></p> <p><i>where</i></p> <p><i>seen</i></p>
Waterways		Breasthooks and Stenson		Pumps <u>2</u>	
Comings		Transoms, Pointers, and Crutches		Boats <u>5</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c. <u>Good</u>	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <u>by inspection and weighing</u>	
Planksheers		Keelsons <u>part seen</u>		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B. 1 S. 1 K.</u>	
Topsides		Ceiling <u>part seen</u>		Cables	
Wales		Rudder <u>Had good</u>		Hawsers and Warps	
Plank (Bottom) and Counter		Copper and G.M. When put on <u>1866</u>		Standing & Running Rigging <u>overhauled</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where seen</u>				

She is now in good and efficient condition, and fit in my opinion to remain Classed A.1.
Joseph Allen.

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 3rd September 1867

Character assigned B.A.1 M.S.



© 2021

Lloyd's Register
Foundation

LN652-0265