

28676

Composite. (Annual)

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 550 Survey held at London Date 31st Aug to 1st Oct 1867
on the Ship "Sobraon" Master J. A. Elmstie
Tonnage 2130 Built at Aberdeen When built 1866 (4 mo)
By whom built Hall Owners Shaw and Co
Port belonging to London Destined Voyage Sidney
If Surveyed Afloat or in Dry Dock Green's upper dry dock and East India Dock

Last Survey, No. 2304 Port Aberdeen Classed 13.A.1 (P.66.)

REPAIRS Now done.

Sighted the greater part of bottom (there being about 4 feet of water in the Dock) the Yellow Metal patched

Renewed 45 fath^{rs} of 2 1/2" Chain Cable tested to 46, 10, 0, 0 at Lloyds Tyne P.C. and An^r Lc Certificate 2386 Sept^r 23rd 1867 Signed R. Durrell.

Rower Anchor 40, 0, 23 tested to 35, 15 at Lloyds Tyne P.C. and Anchor Lc Certificate 5025 Sept^r 23rd 1867. R Durrell.

The Hold considerably lumbered, and Cement in bottom not seen.

Present Condition of the

Decks	<i>Good where seen</i>	Treenails <i>Scum holt</i>	<i>Good where seen</i>	Windlass and Capstan	<i>Good and sufficient where seen</i>
Waterways		Breasthooks and Stenson		Pumps <i>2 M, 2 F, 2 large</i>	
Comings		Transoms, Pointers, and Crutches		Boats <i>7</i>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c. <i>Good</i>	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <i>inspⁿ and enquiry</i>	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of <i>4 R. 10. 11</i>	
Topsides		Ceiling		Cables <i>15 fath^s of 2 1/2" renewed</i>	
Wales		Rudder <i>42 good</i>		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <i>Y. M.</i> When put on <i>1866</i>		Standing & Running Rigging	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <i>Good where seen.</i>			

She is now in good and efficient condition, and fit in my opinion to remain as Classed, 13.A.1.

Joseph Allen.

The Amount of Fee.....£..... is received by me,
Special...../ - / - 0

Certificate (if required)

Committee's Minute 11th October 18 67.

Character assigned 13 A 1