

28684

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 209 Survey held at London Date Sept^r 27th 18 67
on the Rsk "Persia" Master J. Indson
Tonnage 530 Built at Scarbro' When built 1838
By whom built Indall Owners Indall & Co
Port belonging to Scarbro Destined Voyage _____
If Surveyed Afloat or in Dry Dock On Pontons Victoria Dock

Last Survey, No. 27220 Port London Classed 12 A1
G.4. 1.66

REPAIRS

haulked from keel to Planksheer and re-sheathed with Yellow metal

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto Ditto at other places _____	Condition, how ascertained <u>from enquiry & as seen from deck</u>
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors No. of <u>3 B. 1 S. 2 K</u>
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper <u>YM</u> When put on <u>1867</u>	Standing & Running Rigging _____
General Observations and Opinion, _____	Caulking of Bottom, Deck, & Waterways. <u>where tested good</u>	

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£ — : — : is received by me. John Maxwell
Special..... 1 : 1 : 0 MS

Certificate (if required) : :

Committee's Minute 11th October 18 67

Character assigned R. 1
record MS

