

REPORT of SURVEY for REPAIRS.

28717

No. in Reg. Book. **No.** 365 Survey held at London Date 20th Sept - 22nd Oct 1864
 on the Ship "Highflyer" Master Harrison
 Tonnage 1012 Built at London When built 1861. (10 mo)
 By whom built Green Owners Green and Co
 Port belonging to London Destined Voyage Melbourne
 If Surveyed Afloat or in Dry Dock Greens Up^r dry Dock and East India St^s

Last Survey, No. 27979 Port London Classed B. A. 1. (12.66)
 REPAIRS Now done.

Sighted bottom the Yellow Metal patched, and
 payed with peacocks patent paint.
 Caulked the butts of topsides, and deck, &c.
 Renewed the upper main top sail yard with
 Red-pine
 Hold much lumbered with ballast &c.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps <u>5</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>4</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>inspⁿ and enquiry</u>
Planksheers	Keelsons <u>not seen</u>	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B. 10. 1/2</u>
Topsides	Ceiling <u>part seen</u>	Cables
Wales	Rudder <u>Had good</u>	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>Y.M.</u> When put on <u>1866</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where seen.</u>	

She is now in good and efficient condition
 and fit in my opinion to remain Classed A. 1.

The Amount of Fee.....£ : : is received by me,

Special.....

Certificate (if required) : :

Committee's Minute 25th October 1864

Character assigned B. A. 1. M.S.



© 2021

Lloyd's Register
 Foundation

LON652-0389