

2918

REPORT of SURVEY for REPAIRS.

No. in Book. **No.** 35 Survey held at LONDON Date 22nd April to 6th May 1868.
 on the Ship "Lyburnia" Master J. Stephens
 Tonnage 1027 built at Glasgow When built 1857.
 By whom built 962 Owners Somers B.^{rs} 24 New St.
 Port belonging to LONDON Destined Voyage Shang Haie
 If Surveyed Afloat or in Dry Dock Caulked dry Dock and East India Sts

last Survey, No. 26339 Port LONDON. Classed 14. A. 1 (P. 64)
 REPAIRS Now done.

The Yellow Metal stripped, Caulked from steel to metal line, and bottom resheathed with yellow metal only.

Rudder lifted and examined

Renewed the Main-topmast with Pitch-pine and the Fore-topgallant yard with Red-pine.

Windlass stripped, main piece examined, new linings etc.

Memo H. J. Augth 1864.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Shipped
Comings	Transoms, Pointers, and Crutches	Pumps
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Boats <u>2</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Masts, Yards, &c. <u>Good</u>
Planksheers	Keelsons <u>not seen</u>	Condition, how ascertained <u>in fore and aft</u>
Sheerstrakes	Clamps and Shelves	Sails
Topsides	Ceiling <u>part seen</u>	Anchors No. of <u>3 B. 1 C. 1</u>
Wales	Rudder <u>He good</u>	Cables
Plank (Bottom) and Counter	Copper <u>Y.M.</u> When put on <u>now</u>	Hawsers and Warps
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where tested.</u>	Standing & Running Rigging

She is now in good and efficient condition and fit in my opinion to remain as classed. Vis. A. 1.

The Amount of Fee.....£..... is received by me,

Special.....1-1-0

Certificate (if required)

Committee's Minute 15th May 1868.

Character assigned 14 A 1 record MS