

# REPORT of SURVEY for REPAIRS.

29216

No. in Reg. Book. **No.** 54 Survey held at London Date April 22<sup>nd</sup> to May 22<sup>nd</sup> 1868  
 on the BK "Lady Head" Master J James  
 Tonnage 457 built at Southwick When built 1865 (3 mo)  
 By whom built Mills Owners Hud. Bay. Co.  
 Port belonging to London Destined Voyage Hudson Bay  
 If Surveyed Afloat or in Dry Dock Nigrauns dry Dock West India St  
 Last Survey, No. 14821 Port Liverpool Classed B. A. 1 (4.67)  
 REPAIRS None done.

On account of damage Renewed the Rudder, the main piece being Eng<sup>h</sup> Oak; substituted Iron pintles and braces, in lieu of metal.

Sighted bottom; the timbers and all air courses cleared.

Renewed the Stock to Stream Anchor

## Present Condition of the

Decks	} <i>good where seen</i>	Treenails	} <i>good where seen</i>	Windlass and Capstan	} <i>good and sufficient where seen</i>
Waterways		Breasthooks and Stemson		Pumps <u>2</u>	
Comings		Transoms, Pointers, and Crutches		Boats <u>3</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. <u>6 7 8 15 24</u>	
Topsides		Ceiling		Cables	
Wales		Rudder <u>new</u>		Hawsers and Warps	
Plank (Bottom) and Counter		<del>Copper Blacking</del> when put on		Standing & Running Rigging	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where seen</u>				

She is now in good and efficient condition and fit in my opinion to remain as Classed, A. 1.

The Amount of Fee.....£ : : is received by me,  
 Special.....1. 1. 0  
 Certificate (if required) : : : *J. New.*

Committee's Minute 26<sup>th</sup> May 18 68  
 Character assigned 13 A 1