

REPORT of SURVEY for REPAIRS.

29273

No. in Reg. Book. **No.** 187 Survey held at London Date June 22nd 1868
 on the S. "Art Union" Master J. Madron
 Tonnage 748 built at Sunderland When built 1857
 By whom built _____ Owners Sidgell & Son
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Carters & E. J. Dock

Last Survey, No. 28333 Port London Classed 13 A 8

REPAIRS

6.67

Yellow metal repaired, one house pipe and the fore and fore topmasts removed.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>TM + p F</u> When put on <u>1867</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where seen</u>	

This vessel is eligible in my opinion to remain as classed 13 A 8

The Amount of Fee.....£ : : is received by me,
 Special..... : :
 Certificate (if required) : :

Thos. Ar. Wain

Committee's Minute 24th June 1868

Character assigned _____



© 2019
Deferred WMS
 Lloyd's Register
 Foundation

CON653-0276