

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 121 Survey held at London Date June 10th to July 8th 1868
 on the Ship "Newcastle" Master C. E. French
 Tonnage 1137 built at Sunderland When built 1859
 By whom built Pile Jnr Owners R. Green
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Green's Upper dry Dock and East India Dock

Last Survey, No. 28640 Port London Classed B. A. 1. (9.6%)

REPAIRS Now done.

Sighted bottom the Yellow Metal patched and payed with "Peacocks" patent paint.

Caulked the topsides and waterway seams.

Renewed the Main Topsail Yard with Red-pine.

Menu H. T. 9.6%.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps <u>2</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>7</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>inspⁿ and enquiry</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B. 18. 11</u>
Topsides	Ceiling	Cables
Wales	Rudder <u>As good</u>	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>As good</u> When put on <u>1867</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where seen.</u>	

She is now in good and efficient condition and fit in my opinion to remain as Classed Viz. A. 1.

The Amount of Fee.....£ : : is received by me,

Special.....

Certificate (if required) : :

Committee's Minute 10th July 1868

Character assigned 13 A 1 W



© 2019

Lloyd's Register Foundation
LON653-0303