

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 445 Survey held at London Date May 26th 18 68
 on the S "Hotsper" Master Stoddart
 Tonnage 1142 built at Newcastle When built 1857
 By whom built Smith Owners Smith
 Port belonging to Newcastle Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Green's lower & East India Dock

Last Survey, No. 28514 Port London Classed B 21

REPAIRS

Cont 64. 9
7. 65

Stripped Yellow metal sheathing caulked from keel to third beam of deck and re-sheathed with Yellow metal over part felt and part paper.

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>where seen Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>from survey of sea and ground</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B, 1 S, 2 K</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>YM over pt felt</u> When put on <u>1868</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where tested Good</u>	

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : :

Committee's Minute 21st July 18 68

Character assigned Cont 19 1

record



© 2019

Lloyd's Register Foundation