

REPORT of SURVEY for REPAIRS.

29413

No. in Reg. Book. **No.** 35 Survey held at London Date 13th Aug^h 21st 1868
 on the Brig Narcissus Master A. Cooper
 Tonnage 187 built at Scarbro When built 1836
 By whom built _____ Owners Jindalls
 Port belonging to Scarbro Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Carters dry dock & afloat

Last Survey, No. 2353 Port London Classed 11.1.1 orig^l Cont^d 4.1.1 in 1860 and E.1.1/61.
 REPAIRS Clap omitted

Now done. hung her Caulked up to upper part of doubling planks. likewise the deck. Cut out all ceiling planks found bad or the defects therefrom. on the Starbd side opened her inside below and found the timbers in a good state of preservation, two choers to fullth feet renewed (one on each side), five new lengths of ceiling planks introduced on the Starbd, four on the Port side, and several gone pieces both sides, eight new lengths of deck planks, on the Starbd, and four on the Port side fitted. lifted the Bowsprit gave her a new one of Pitch pine. and put the rigging in order.

Present Condition of the

Decks	<u>good</u>	Treenails	<u>when seen</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	<u>nearly new</u>
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	"
Planksheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of <u>3</u>	"
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder	<u>nearly new</u>	<u>effcty</u>	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<u>Set & doubled</u>	<u>When put on 158</u>	Standing & Running Rigging	"

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good.

She has apparently been kept in repair since going off the Clap, and is now in an efficient state, and fit in my opinion for the conveyance of dry and perishable Cargoes, and is

The Amount of Fee.....£ : 10: } is received by me.

Special..... 1 : 1: }

Certificate (if required) : 2: }

Committee's Minute 1st September 1868

Character assigned A. 1

record repairs RP



© 2019

Lloyd's Register Foundation

LONG653-0377