

29458

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 521 Survey held at London Date Sept- 11th 18 68
on the "Christine" Master Kennedy
Tonnage 386 built at Southwick When built 1863
By whom built _____ Owners Hanky &
Port belonging to London Destined Voyage St Helena
If Surveyed Afloat or in Dry Dock Nelson dock & W. J. Dock

Last Survey, No. 28582 Port London Classed 11A 1
REPAIRS 9. 67

*Yellow metal repaired and painted
with Peacocks composition.*

Present Condition of the				
Decks	} Good where seen	Treenails	} Good where seen	
Waterways		Breasthooks and Stemson		
Comings		Transoms, Pointers, and Crutches		
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		
Lower Deck Beams & Fastenings		Ditto Ditto at other places		
Planksheers		Keelsons		
Sheerstrakes		Clamps and Shelves		
Topsides		Ceiling		
Wales		Rudder		
Plank (Bottom) and Counter		Copper <u>T. & YNE</u> When put on <u>1866</u>		
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <u>good where seen</u>		
Windlass and Capstan	} Good and sufficient	Pumps		
Boats		Masts, Yards, &c.		
Condition, how ascertained		Sails		
Anchors No. of		Cables		
Hawsers and Warps		Standing & Running Rigging		

*This vessel is eligible in my opinion
to remain classed 11A 1*

The Amount of Fee.....£ : : is received by me, Mrs. W. W. Wain
Special..... : :
Certificate (if required) : :

Committee's Minute 15th September 1868
Character assigned 11A 1 WAS

