

# Half-time Survey.

## REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 360 Survey held at London Date Aug<sup>r</sup> 8<sup>th</sup> to Sept<sup>r</sup> 14<sup>th</sup> 1868  
 on the Ship Highflyer Master W. Harrison  
 Tonnage 1012 built at London When built 1861  
 By whom built Green Owners Green & Co  
 Port belonging to London Destined Voyage Melbourne  
 If Surveyed Afloat or in Dry Dock Green's upper dry dock & E.I. Dock

Last Survey, No. 28717 Port London Classified 13 A 1  
67

REPAIRS now done, The hold cleared, stages made, listings cut at each end of the hold for one-fifth her length, five dozen treenails driven out from various parts, the windlass mthung and stripped, chains ranged and examined, and all other requirements of the rule Sec 34 complied with, We did not think it necessary to have any portion of the Teak topsides scraped -  
 Caulked from the metal line over to metal line -

### Present Condition of the

Decks <u>caulked</u>	} <u>good</u>	Treenails <u>good where seen</u>	Windlass and Capstan <u>good</u>
Waterways <u>do</u>		Breasthooks and Stemson	Pumps <u>and</u>
Comings <u>do</u>		Transoms, Pointers, and Crutches <u>good</u>	Boats <u>efficient</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings	Masts, Yards, &c. <u>by observation from deck</u>
Lower Deck Beams & Fastenings <u>where</u>	} <u>where</u>	Ditto Ditto at other places	Condition, how ascertained <u>good</u>
Planksheers <u>caulked</u>		Keelsons	Sails <u>and</u>
Sheerstrakes <u>do</u>		Clamps and Shelves	Anchors No. of <u>3 B 1 S 2 K</u>
Topsides <u>do</u>		Ceiling	Cables <u>sufficient</u>
Wales <u>do</u> <u>seen</u>	Rudder <u>seen</u>	Hawsers and Warps	
Plank (Bottom) and Counter	Copper <u>YM</u> When put on <u>1866</u>	Standing & Running Rigging	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

She is now in good and efficient condition fit in our opinion to remain as classed 13 A 1. and to be marked (HT 1868) in the

The Amount of Fee.....£ : : is received by me, Registered Book  
 Special.....2 : 2 :  
 Certificate (if required) : 5 :

Committee's Minute 18<sup>th</sup> September 1868

Character assigned 13 A 1

HT 62