

29520

REPORT of SURVEY for REPAIRS.

in Book. No. 29127 Survey held at London Date August 8th 1868
on the Y3rd "Cardoanshire" Master J. Jenkins
Tonnage 365 built at Hayland When built 1864
By whom built J. Jenkins Owners J. Jenkins
Port belonging to London Destined Voyage London Dock
If Surveyed Afloat or in Dry Dock Fountain dry dock & London Dock

Survey, No. 29127 Port London Classed 14 A 1
3.68.

In consequence of damage, see Special Report; the keel and false keel removed with Elm, a few treenails and additional bolts driven in bilges - The caulked from keel to metal line and resheathed with yellow metal on felt

at Condition of the

ways	Good where seen	Treenails	Good where seen	Windlass and Capstan	Good and sufficient
gs		Breasthooks and Stenson		Pumps	
Deck Beams & Fastenings		Transoms, Pointers, and Crutches		Boats	
Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
heers		Ditto Ditto at other places		Condition, how ascertained	
akes		Keelsons		Sails	
es		Clamps and Shelves		Anchors No. of	
(Bottom) and Counter		Ceiling		Cables	
		Rudder		Hawsers and Warps	
		Copper <u>14 J M</u> When put on <u>now</u>		Standing & Running Rigging	

Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is now in good condition and is eligible in my opinion to remain classed

Amount of Fee.....£ 1 : - : - is received by me,

Special ~~damage~~ 3 : 3 : 3/6

Certificate (if required) : : 3/6

Committee's Minute 13th October 1868

Character assigned 14 A 1

Jos. W. Wain

(record damage repairs)