

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 527 Survey held at London Date Decr 15th 18 68
 on the S. J. Husan Master Roy
 Tonnage 817 built at Birkenhead When built 1865
 By whom built Flayton Owners Brit. & Eastern Co
 Port belonging to Liverpool Destined Voyage Hong Kong
 If Surveyed Afloat or in Dry Dock in Union & West India Dock

Last Survey, No. 28804 Port London Classed 14 A1
c.f. Iron Fram Planked 11. 67

REPAIRS

Generally examined this vessel and found all appearing in good and firm condition, no signs of working being visible and the Yellow metal sheathing being in good order.

Present Condition of the

Decks <u>where seen Good</u>	Freenails <u>Bolts</u> <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>from engine & as seen from deck</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3/3, 18, 2K</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>F & Y M</u> When put on <u>1867</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where seen Good</u>	

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£ : : is received by me, John Maxwell

Special..... : :

Certificate (if required) : :

Committee's Minute 22nd December 18 68

Character assigned 14 A 1



© 2019

Lloyd's Register Foundation

LN654-0016