

ANNUAL SURVEYS.

29798

Rev 12.2.69

No. 105 Survey held at London Date February 11th 1869
 on the Composite Ship "Lake Seaman" Master Malcolm
 Tonnage 1073 Built at Newfrew When built 1867
 By whom built Simons Owners Young & Co
 Port belonging to Glasgow Destined Voyage London
 If Surveyed Afloat or in Dry Dock Thames Dry Dock

Last Survey, No. 2631 Port of Glasgow Classed 14 AI

The present Condition of the

Decks	<u>good</u>	Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	<u>good</u>
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c. <u>seen from the deck good</u>	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	<u>Sufficient</u>
Planksheers		Keelsons		Anchors No. of <u>3 B. 15. 2 H.</u>	
Sheerstrakes		Clamps and Shelves		Cables	<u>Sufficient</u>
Topsides		Ceiling		Hawsers and Warps <u>good</u>	<u>Sufficient</u>
ales		Rudder		Standing & Running Rigging	<u>good</u>
Plank (Bottom) and Counter		Copper <u>Yellow Metal</u> When put on <u>1867</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Patched Yellow Metal, - And is now in good order and condition and eligible to remain as Classed 14 AI

Committee's Minute 16th February 1869

Character assigned 14 AI 1 MAS

Wm. J. Tucker

Certificate (if required)

No. 86 Survey held at London Date 11th February 1869
 on the Wood Ship General Caulfield Master E. Moon
 Tonnage 647 Built at Shields When built 1859
 By whom built Smith Owners F. Smith, Southern
 Port belonging to London Destined Voyage London to India
 If Surveyed Afloat or in Dry Dock Green's Dry Dock

Last Survey, No. 29133 Port of London Classed 14 AI

The present Condition of the

Decks	<u>good</u>	Treenails		* Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	<u>good</u>
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c. <u>seen from the deck good</u>	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	<u>Sufficient</u>
Planksheers		Keelsons		Anchors No. of <u>3 B. 15. 2 H.</u>	
Sheerstrakes		Clamps and Shelves		Cables	<u>Sufficient</u>
Topsides		Ceiling		Hawsers and Warps <u>good</u>	<u>Sufficient</u>
ales		Rudder		Standing & Running Rigging	<u>good</u>
Plank (Bottom) and Counter		Copper <u>Yellow Metal</u> When put on <u>1867</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Patched and Painted Yellow Metal, - And is now in good order and condition, and, eligible in my opinion to remain as classed 14 AI

Committee's Minute 16th February 1869

Character assigned 14 AI 1 MAS

Wm. J. Tucker

Certificate (if required).