

REPORT of SURVEY for REPAIRS.

No. in
Reg. Book. **No.** Survey held at London Date 22nd April 18 69

on the Ship "Saladun" Master J. Rankin

Tonnage 752 built at Sunderland When built 1857

By whom built Owners Menderson

Port belonging to London Destined Voyage Calcutta

If Surveyed Afloat or in Dry Dock Princes Dry dock and East India docks.

Last Survey, No. 21331 *Port* Liverpool *Classed* B.A.

REPAIRS

Ref. 64 -- 9 yrs ✓
cf. 5-68

Hold cleared proper stages made both inside and outside. The timbers and all air courses cleared. outside planking scraped bright in various parts. Treennails driven out as per Rule. Mudlars unhung, wood linings stripped and chain cables ranged on deck, for Examination.

Shipped Yellow Metal Sheathing, Windlass renewed
of Iron Bark; caulked from keel to waterway-keam also Prop
and Forecastle drifts, and resheathed bottom with Yellow
Metal on felt.

Fore Mast, fore topmast and cross-jack yards
renewed of Pine.

Present Condition of the

Decks _____

Waterways _____

Comings _____

Upper Deck Beams & Fastenings _____

Lower Deck Beams & Fastenings _____

Planksheers _____

Sheerstrakes _____

Topsides _____

Wales _____

Plank (Bottom) and Counter _____

Treenails _____
 Breasthooks and Stemson _____
 Transoms, Pointers, and Crutches _____
 Timbers of the Frame at the openings _____
 Ditto Ditto at other places _____
 Keelsons _____
 Clamps and Shelves _____
 Ceiling _____
 Rudder _____
 Copper *4 lb* When put on *horr*

Windlass and Capstan _____ *Good*

Pumps _____ *— —*

Boats _____ *— —*

Masts, Yards, &c. _____ *— —*

Condition, how ascertained *examined aloft.*

Sails _____

Anchors No. of _____

Cables _____

Hawsers and Warps _____

Standing & Running Rigging _____


*Good
and
Sufficient*

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested

Is now in good and efficient condition and in my opinion eligible to remain as classified and be marked H.T. 69

The Amount of Fee.....£ : : is received by me,

Special..... 3 : 3 : {  24/4/69

Certificate (if required) : 5 :

Committee's Minute 27 April 18 69

Character assigned

Comp
H. 9 1 11 14
recd. 11/11/11

© 2019

Lloyd's Register
Foundation

LON654-0233