

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 453 Survey held at London Date 31st March Aprilth 1869
 on the Ship Tyburnia Master J. Stevens. Esq.
 Tonnage 1027 built at Glasgow When built 1857
 By whom built 962 Owners Merchant Shipps. Co. Ltd.
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock Canal dry dock & East India Docks.

Last Survey, No. 29184 Port London Classed 14. A. 1.
 REPAIRS 5. 68

*Pasch'd and repaired the Yellow metal sheathing
 Condemn'd the main piece of Rudder which was found badly decay'd
 Introduced a New main piece of English Oak. Refitted it. also
 the Steering Wheel.*

Present Condition of the		Windlass stripped 1864	
Decks	<i>good</i>	Treenails	<i>where seen good</i>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	<i>firm</i>	Timbers of the Frame at the openings	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder	<i>efficient</i>
Plank (Bottom) and Counter	"	Copper	<i>7th Mil When put on 1868.</i>
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <i>good</i>	
		Windlass and Capstan	<i>in good order</i>
		Pumps	"
		Boats	"
		Masts, Yards, &c.	"
		Condition, how ascertained	<i>from the Deck</i>
		Sails	"
		Anchors No. of	<i>3 & 1 S. 1. R. 1.</i>
		Cables	"
		Hawsers and Warps	"
		Standing & Running Rigging	"

*As far as seen she appears in good Condition, and is in
 my opinion entitled to remain as Class'd 14. A. 1.*

The Amount of Fee.....£ — : — } is received by me,
 Special..... 1 : 1 : }
 Certificate (if required) : : }

Committee's Minute 25th May 18 69
 Character assigned 14 A 1 MAY



Tyburnia

