

30159

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 570 Survey held at London Date 1<sup>st</sup> June 1869  
on the  bark. 'Priscilla' Master Geo. Brown  
Tonnage 253 built at Wells When built 1858  
By whom built A Owners Bullard & Co  
Port belonging to London Destined Voyage Port Natal  
If Surveyed Afloat or in Dry Dock Horseferry dry dock and Afloat.

Last Survey, No. 29325 Port London Classed B.A.I.  
Contn<sup>d</sup> 68-- 7 yrs.  
7.68

## REPAIRS

For Damage

Stripped Yellow Metal sheathing the fore and after lengths of Main keel renewed of English Elm, thro fastened with Yellow Metal bolts, and the garboard strake in way of same on Port side, together with one short fore hood of ditto on Starb<sup>d</sup> side of Larch. Hung in shores caulked from keel to second beam within waterway beam and resheathed bottom with Yellow Metal on Teak.

The remaining portion of flat of Upper deck caulked, but not to be included in the damage.

### Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

*Work where done* (written diagonally across the left column)

*Work where done* (written diagonally across the middle column)

*Look* (written above Windlass and Capstan)

*See from the deck* (written above Condition, how ascertained)

*Look and Sufficient* (written above Anchors, Cables, Hawsers and Warps)

*Look where tested* (written above Caulking of Bottom, Deck, & Waterways)

*Is now in good and efficient condition and in my opinion eligible to remain as Classed.*

The Amount of Fee.....£ 10 : is received by me,  
Special.....£ 2 : 2 :  
Damage.....£ 2 : 2 :  
Certificate (if required).....£ : :  
*RP Turner*

Committee's Minute 11<sup>th</sup> June 1869

Character assigned Cont<sup>d</sup> 7

*record damage repair*



© 2019

Lloyd's Register Foundation

LON654-0313