

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 239 Survey held at London Date 15<sup>th</sup> June 19<sup>th</sup> 1869  
 on the Ship Peterborough Master B. Orchard,  
 Tonnage 560 built at Sunderland When built 1859  
 By whom built Austin Owners Hankey,  
 Port belonging to London Destined Voyage Hong Kong.  
 If Surveyed Afloat or in Dry Dock Commercial dry dock & afloat.

Last Survey, No. 29209 Port Lon. Classed 13. A. 1.  
68

## REPAIRS

Stripped off the whole of the Yellow Metal Sheathing.  
 Caulked up to metal line, and resheathed with Yellow  
 Metal on felt. — (Hung her in Shores)

### Present Condition of the

Decks	<u>good</u>	Treenails	<u>where seen</u>	<u>good</u>	Windlass and Capstan	<u>stripped in 1866</u> <u>in good order</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	<u>firm</u>	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	"
Planksheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of <u>3 L -</u>	"
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder	<u>efficient</u>	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<u>Set by M<sup>r</sup> Hankey</u>	<u>When put on Now.</u>	Standing & Running Rigging	"
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.				<u>good where tested.</u>

She appears, as far as seen, to be in good condition and is in  
 my opinion entitled to remain as Class'd 13. A. 1.

Samuel Presons

The Amount of Fee.....£ : : } is received by me,  
 Special..... / : / : }  
 Certificate (if required) : : }

Committee's Minute 29<sup>th</sup> June 18 69

Character assigned 13 A 1 record Mr MAS



© 2019

Lloyd's Register  
 Foundation

LONG54-0356