

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 67 Survey held at London Date 25th June 18 69
 on the Ship "Dartmouth" Master Elsdon
 Tonnage 933 built at Dundee When built 1859
 By whom built Stephen Owners Somes Br
 Port belonging to London Destined Voyage ✓
 If Surveyed Afloat or in Dry Dock Canal dry dock

Last Survey, No. 29043 Port London Classed 14 A
 68

REPAIRS

Yellow Metal Sheathing stripped and recaulked from keel to underside of Topsides, re sheathed with Yellow Metal on Felt

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>good</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>from deck</u>
Planksheers	Keelsons	Sails <u>sufficient</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3131 & 2A</u>
Topsides	Ceiling	Cables <u>sufficient</u>
Wales	Rudder	Hawsers and Warps <u>good</u>
Plank (Bottom) and Counter	Copper <u>Yellow Metal</u> When put on <u>1869</u>	Standing & Running Rigging <u>good</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good when seen</u>	

Is now in good order and condition and eligible in my opinion to remain as Classed 14 A

The Amount of Fee.....£ 1 : 1 : 0 is received by me,

Special.....

Certificate (if required)

Committee's Minute 16th July 18 69

Character assigned 14 A



© 2019

Lloyd's Register Foundation

LON654-0380