

REPORT of SURVEY for REPAIRS.

30273

No. in Reg. Book. 380 No. 29464 Survey held at London Date, first Survey June Last Survey July 3rd 1869
 on the Highflyer Master Harrison
 Tonnage 1012 built at London When built 1861
 By whom built Green Owners Green & Co
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Greens dry dock
 Last Survey, No. 29464 Port Lon. Classed 13A1 HT 68
 REPAIRS, &c.

*Vessel in dry dock Yellow Metal Sheathing
 Stopped and caulked from Keel to Gunwale
 Resheathed with Yellow Metal on Felt.*

Present Condition of the

Decks	<i>Good when seen</i>	Treenails	<i>Good when seen</i>	Windlass and Capstan	<i>Good</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <i>Yellow Metal</i> When put on <u>1869</u>		Standing & Running Rigging	
Engine Room Skylights	Caulking of	Cargo and Main Hatchways	Hatches		
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	<i>Good</i>	<i>Good</i>	<i>Good</i>	

General Observations and Opinion,

*Is now in good order and condition and eligible
 in my opinion to remain as classed 13A1 HT*

The Amount of Entry Fee.....£ : : is received by me.

Special..... 1 : 1

Certificate (if required) : 5 :

Committee's Minute 3rd August 18 69.

Character assigned 13

record G. M.



© 2019

Lloyd's Register
Foundation

LN654-0408