

30386

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 87 Survey held at London Date 9th Sep^r 24th 1869
on the Barque Verulam Master Mr. Creak
Tonnage 312 built at Burton Stather When built 1865
By whom built Wray Owners Bullard &
Port belonging to London Destined Voyage Nasal
If Surveyed Afloat or in Dry Dock Horse Ferry and St Katharines

Last Survey, No. 28957 Port Lon. Classed 11. A. 1. c. f. 68

REPAIRS

Now done. Paschid or made good the Yellow metal Sheathing
overhauled the Caulking of Poop drifts. Topsides &c. - Waterway
seams.

Present Condition of the

Decks	<u>good</u>	Treenails	<u>where seen</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	<u>from the Deck</u>
Planksheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of <u>3 &</u>	"
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder	<u>efficiently</u>	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<u>2 1/4 in</u>	When put on <u>1868</u>	Standing & Running Rigging	"
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good</u>					

We are of opinion she is entitled to remain as Class'd
11. A. 1.

Samuel Presious

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 28th September 1869

Character assigned 11A / 1MA



© 2021

Lloyd's Register

Foundation