

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 749 Survey held at London Date 28th Feb^r Oct^r 9th 1869
 on the Barque Star of Devon Master W. Robilliard
 Tonnage 339 built at Plymouth When built 1864
 By whom built Skilsm Owners Standwick
 Port belonging to London Destined Voyage Algoa Bay
 If Surveyed Afloat or in Dry Dock Smiths Dry Dock

Last Survey, No. 941 Port Gloster Classed B.A.I.
 1, 68

REPAIRS

Survey'd her in ballast.

Sighted the yellow metal, patch'd and repaired it, and made all good and efficient

Present Condition of the

Decks	<i>good</i>	Treenails	<i>where seen</i>	<i>good</i>	Windlass and Capstan	<i>in good order</i>
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	<i>firm</i>	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	<i>from the Deck</i>
Planksheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of <u>3</u>	"
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder	<i>efficient</i>	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<i>Let & gilt</i>	When put on <u>1868</u>	Standing & Running Rigging	"
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <i>good.</i>				

As far as seen, she appears to be in good condition and is in my opinion, entitled to remain as class'd B.A.I.

The Amount of Fee.....£ — : — : } is received by me,
 Special..... / : / : }
 Certificate (if required) — : — :

Samuel Presins

Committee's Minute 19th October 18 69

Character assigned 13 A 1



© 2021

Lloyd's Register Foundation

LON 655-0052