

# REPORT of SURVEY for REPAIRS.

31025

No. in Reg. Book. 204 No. 30294 Survey held at London Date, first Survey 21<sup>st</sup> June Last Survey 13<sup>th</sup> July 18 90  
on the Ship "Astérope" Master Homer  
Tonnage 601 built at Aberdeen When built 1859  
By whom built A. Hall & Owners Parker & Co.  
Port belonging to London Destined Voyage Auckland  
If Surveyed Afloat or in Dry Dock Green's Upper Dry Dock.

Last Survey, No. 30294 Port Lon. Classed 13 A 1.  
Windlass stripped - { Report  
5, 69. 27440.

REPAIRS, &c. Vessel caulked to metal line, and bottom re-installed on felt.

## Present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	} <u>Good and complete</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides	} <u>seen.</u>	Ceiling	} <u>where seen.</u>	Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter	} <u>seen.</u>	Copper <u>4. M. on 7.</u> When put on <u>Now.</u>	} <u>Good</u>	Standing & Running Rigging	
Engine Room Skylights		Caulking of		Cargo and Main Hatchways <u>Good</u> Hatches <u>Good.</u>	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>Good where tested.</u>	Scuppers <u>Good</u>			

General Observations and Opinion, Is now in good and efficient condition, and fit in my opinion to remain as classed - 13 A 1.

J. H. Eastlake.

The Amount of Entry Fee.....£ 1 is received by me,

Special..... 1

Certificate (if required) 5

Committee's Minute 12<sup>th</sup> August 18 90

Letter assigned 13 A 1