

31025  
JF

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 269 No. 102 Survey held at London Date, first Survey July 27 Last Survey Aug<sup>th</sup> 3<sup>rd</sup> 1870  
on the Ship Celaeno Master C. Renault  
Tonnage 702 built at Aburdeen When built 1863  
By whom built Hall Owners J. & D. Parker  
Port belonging to London Destined Voyage Wellington  
If Surveyed Afloat or in Dry Dock Greens upper Dock & East India Docks.  
Last Survey, No. 30346 Port Lon. Classed 13. A. 1. C. 1  
REPAIRS, &c. Surveyed in ballast

Sighted the Yellow Metal Sheathing, which appears to be unwrinkled, and in a satisfactory state for the Voyage.  
Lifted the Chain Cables from the lockers. Ranged them and found them sufficient in size and in quantity also.  
Unlashing the Windlafs, stripped off the linings examined the main pieces, also the Pall and Garrick bits. - and as far as seen, found the whole in a satisfactory condition. - Caulked topsides.  
(The spindle of the Windlafs passes through)

## Present Condition of the

Decks	good	Treenails	where seen good	Windlass and Capstan	in good order.
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	firm	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	from the Deck "
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of	3 & 1 S. 2 K. "
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder	efficient	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Gopper	When put on 1868	Standing & Running Rigging	"
Engine Room Skylights		Caulking of	good	Cargo and Main Hatchways	good
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways		Hatches	good
General Observations and Opinion,		Scuppers	good		

As far as seen she appears to be in good condition and is in my opinion entitled to remain as classed 13. A. 1.  
Tanner Presious

The Amount of Entry Fee.....£ — : — : is received by me,  
Special..... 1 : 1 : }  
Certificate (if required) : 5 : }

Committee's Minute 12<sup>th</sup> August 18 70  
Character assigned 13 A 1



Celano

# REPORT OF SURVEY FOR REPAIRS



© 2021

Lloyd's Register  
Foundation