

Composite 31028

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 697 Survey held at London Date August 3rd 1870
 on the S. "Michael Angelo" Master Luckie
 Tonnage 1174 built at Glasgow When built 1865
 By whom built _____ Owners Lidgett & Sons
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Carters & East India Dock

Last Survey, No. 30359 Port Lon. Classed 16 A 1
 S.S. 68 9.69

REPAIRS

Yellow metal repaired -

Present Condition of the

Decks	<i>Good where seen</i>	Treenails	<i>Good where seen</i>	Windlass and Capstan	<i>Good & sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>F. & T. P.</u> When put on <u>1869</u>		Standing & Running Rigging	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is eligible in my opinion to remain as classed 16 A 1

The Amount of Fee.....£ : : is received by me, Thos. W. Nawn
 Special..... : :
 Certificate (if required) : :

Committee's Minute 12th August 1870
 Character assigned 16 A 1

24 C. P. only not at C.P.