

31035

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 367 No. 1 Survey held at London Date, first Survey July 22nd Last Survey Augst 3rd 1870
on the Barque Prince of Wales Master W. Adamson
Tonnage 509 built at Southampton When built 1850
By whom built — Owners Hudsons Bay Comp^y
Port belonging to London Destined Voyage —
If Surveyed Afloat or in Dry Dock Wigram's dry dock & West India docks.
Last Survey, No. 30290 Port Lon. Classed 13. A. 1. c.f. H.T. 69 Cont'd 63. g. 4. 1.
REPAIRS, &c. 8. 69

Stripped off the Yellow Metal sheathing
Caused the doubling planks. Testeash'd with Yellow Metal
on paper. - Introduced a new Foremast, and a new
mizen, and made good the rigging throughout

Present Condition of the

Decks	good	Treenails	where seen	good	Windlass and Capstan	in good order
Waterways	"	Breasthooks and Stemson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained	from the Deck "
Planksheers	"	Keelsons	"	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	"	Anchors No. of	3 & 1 S. 2 K. "
Topsides	"	Ceiling	"	"	Cables	"
Wales	"	Rudder	efficient	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	put on	now	Standing & Running Rigging	"
Engine Room Skylights	"	Caulking of	good	"	Cargo and Main Hatchways	good
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways	where tested	"	Hatches	good
General Observations and Opinion,	"	Scuppers	good	"		

She is now in good, and efficient condition,
and is in my opinion entitled to remain as class'd 13. A. 1.
Samuel Presious

The Amount of Entry Fee.....£ - - - is received by me,
Special..... / : / :
Certificate (if required) :

Committee's Minute 16th August 1870
Character assigned Cont'd 9 A record 411
W.H.

Primer of Wales

REPORT OF SURVEY FOR REPAIRS



© 2021

Lloyd's Register
Foundation