

31202

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **433** No. **1** Survey held at **London** Date **31st October** 18 **70**
on the **S. "Jubilee"** Master **H. Conterdine Hookman**
Tonnage **764** built at **Worthington** When built **1857**
By whom built **London** Owners **J. Bosdie**
Port belonging to **London** Destined Voyage **Australia**
If Surveyed Afloat or in Dry Dock **Princes dry dock & West India Dock**

Last Survey, No. **29065** Port **Lon.** Classed **14 A 5**
H.T. 68. 3, 68

REPAIRS

Yellow metal stripped off, recaulked from keel to metal line and the yellow metal renewed on Felt.

Present Condition of the

Decks	} <i>Good where seen</i>	Treenails	} <i>Good where seen</i>	Windlass and Capstan	} <i>Good and sufficient.</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <i>T. & M.</i> When put on <i>now</i>		Standing & Running Rigging	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <i>good where seen tested</i>				

This vessel is eligible in my opinion to remain as classed 14 A 5

The Amount of Fee.....£ - : - : is received by me,
Special..... 1 : 1 : } *APD*
Certificate (if required) : 5 : } *14. 11. 70*

Committee's Minute **14th November 1870**
Character assigned **14 A 1**

record this
MA

Thos. H. Wain