

# REPORT of SURVEY for REPAIRS.

31418

No. in Reg. Book. 142 No. 142 Survey held at London Date, first Survey 28<sup>th</sup> Jan<sup>y</sup> Last Survey Feb<sup>y</sup> 2<sup>o</sup> 18 71  
 on the Ship Vimeira Master George Self  
 Tonnage 941 built at Sunderland When built 1851  
 By whom built — Owners Gellarsly & Co.  
 Port belonging to London Destined Voyage Cardiff  
 If Surveyed Afloat or in Dry Dock Canal dry dock  
 Last Survey, No. 30644 Port Low Classed Cons<sup>d</sup> 164-9.5.1.  
 REPAIRS, &c. H.T. 168.

Stripped off the Yellow Metal in wake of the iron breasthooks on both sides, and renewed the Yellow Metal bolts in the same. - Introduced at the after end, two extra yellow metal through bolts on each side in some timbers found slack of securing at the heels. Patched and made good the Yellow Metal Sheathing.

## Present Condition of the

Decks	<u>good</u>	Treenails	<u>where seen</u>	<u>good</u>	Windlass and Capstan	<u>in good order</u>
Waterways	<u>"</u>	Breasthooks and Stemson		<u>"</u>	Pumps	<u>"</u>
Comings	<u>"</u>	Transoms, Pointers, and Crutches		<u>"</u>	Boats	<u>"</u>
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame at the openings		<u>"</u>	Masts, Yards, &c.	<u>"</u>
Lower Deck Beams & Fastenings	<u>"</u>	Ditto Ditto at other places		<u>"</u>	Condition, how ascertained	<u>"</u>
Planksheers	<u>"</u>	Keelsons		<u>"</u>	Sails	<u>"</u>
Sheerstrakes	<u>"</u>	Clamps and Shelves		<u>"</u>	Anchors No. of <u>3 &amp; 1 S. 2 K</u>	<u>"</u>
Topsides	<u>"</u>	Ceiling		<u>"</u>	Cables	<u>"</u>
Wales	<u>"</u>	Rudder <u>efficient</u>		<u>"</u>	Hawsers and Warps	<u>"</u>
Plank (Bottom) and Counter	<u>"</u>	Copper <u>Yel Metal</u> When put on		<u>"</u>	Standing & Running Rigging	<u>"</u>
Engine Room Skylights		Caulking of	<u>good</u>			
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	<u>where tested in wake of breasthooks</u>			
General Observations and Opinion,		Scuppers	<u>good</u>		Cargo and Main Hatchways	<u>good</u>
					Hatches	<u>good</u>

Survey'd her in ballast.

As far as seen she is in good condition and is in my opinion entitled to remain at class'd Cons<sup>d</sup> 164. 9. 5. 1.

Samuel Presons

The Amount of Entry Fee.....£ — : — : is received by me,

Special..... 1 : 1 :

Certificate (if required) : 5 :

Committee's Minute 17<sup>th</sup> February 18 71

Character assigned Cons<sup>d</sup> 9

J.P.

record



© 2021

Lloyd's Register Foundation

LON656-0249



Vincennes



© 2021

Lloyd's Register  
Foundation