

REPORT of SURVEY for REPAIRS.

31421

No. in Reg. Book. 208 No. 208 Survey held at London Date, first Survey 26th Jan Last Survey 11th Feb 1871
 on the Ship "Flying Spur" Master Barnett
 Tonnage 735 built at Aberdeen When built 1860
 By whom built Hall Owners Robertson & Co
 Port belonging to London Destined Voyage Japan
 If Surveyed Afloat or in Dry Dock Nelson Dry Dock

Last Survey, No. 29684 Port Lon. Classed 14 A1.

REPAIRS, &c. Metal stripped. Vessel hung in shores, recaulked from keel to metal line, and remetalled on felt.

H.T. 68.
12, 68.

Present Condition of the

Decks	} <u>Good</u> <u>where</u> <u>seen.</u>	Treenails	} <u>Good</u> <u>where</u> <u>seen.</u> <u>Now.</u>	Windlass and Capstan	} <u>Good and</u> <u>complete</u> <u>where seen.</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>H & G. M.</u> When put on <u>Now.</u>		Standing & Running Rigging	
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways <u>Good when tested</u>	Cargo and Main Hatchways <u>Good</u>	Hatches <u>Good.</u>	

General Observations and Opinion,

Is now in good condition, and fit in our opinion to remain classed 14 A1.

The Amount of Entry Fee.....£ - : - : is received by me,

Special..... / : / : -

Certificate (if required).....

J. H. Eastlake.

[Signature]

Committee's Minute 21st February 1871

Character assigned 14 A1 record [initials]



© 2021

Lloyd's Register Foundation

LN656-0251