

REPORT of SURVEY for REPAIRS.

No. in
Reg. Book.

No.

Survey held at

Date, first Survey

Last Survey

18

on the

Master

Tonnage

built at

When built

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No.

Port

Classed

REPAIRS, &c.

Half time. Scraped bright where required, treenails and bolts driven out for survey, listings cut out 1/5 the length of the ship and all found good, Windlass striped chains ranged and all other requirements of the Rules complied with. Yellow metal stripped off recaulked, from keel to metal line and the yellow metal renewed on belt.

Mixed material

It will be seen by the first entry report that the frame (except the floors and first futtocks) is all of 12 years material also the planking of the wales topsides and sheerstrakes, the inside planking 10 years and the remainder 9 & 10, the whole in my opinion entitling her to the increase of 1 year. Class.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations and Opinion,

Treenails

Breasthooks and Stenson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper T. J. M. When put on

Caulking of

Bottom, Deck, & Waterways

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of 3 & 2

Cables 270 fms

Hawsers and Warps

Standing & Running Rigging

Good & sufficient

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

good

The Amount of Entry Fee.....£

Special..... 4: 4:

Certificate (if required)..... 5: 5:

Committee's Minute

Character assigned

Raise to 11A
Record Y.M.

18

18

18

18

18

18

18

18

18

18

18

Have examined the 1st Entry Report of this vessel and consider her case a very good one for the favourable consideration of the Committee for an additional year under the mixed material rule - say to be required to 11A & 1/2 years material.