

31800

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 144 Survey held at London Date July to Aug 8th 1870
on the Ship "Renown" Master S. Saylor
Tonnage 1293 built at London When built 1860
By whom built _____ Owners Messrs R & H. Green
Port belonging to London Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Last India Dock

Last Survey, No. 29608 Port Lon. Classed 13A.1.
H.T. 68. J. 68

REPAIRS

Now done, the Knee of Head taken down, refitted, and bolted, the Upper Piece of Stem renewed with Seal & -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Good where seen</u>	Breasthooks and Stems	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings } <u>Good</u>	Ditto Ditto at other places	Condition, how ascertained } <u>Good & Sufficient</u>
Planksheers	Keelsons	Sails
Sheerstrakes } <u>Good where seen</u>	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	<u>Yellow Metal</u>	Standing & Running Rigging
	Copper on Felt When put on <u>1866</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

There was a leak in this ship on her last voyage found to proceed from a split in the upper piece of stem, which has now been renewed - She is now in good and efficient condition, fit in my opinion to remain classed 13A.1.

The Amount of Fee.....£ - : - : } is received by me, B. Waymouth
Special..... / : / : }
Certificate (if required) : 5 : }

Committee's Minute 15th August 1871

Character assigned 13A.1