

REPORT of SURVEY for REPAIRS.

31983

No. in Reg. Book. 176 No. 31317 Survey held at London Date, first Survey Oct. 11 Last Survey Nov. 4 1871.
 on the "Agnes Rose" Master H. Purves
 Tonnage 991 built at Aberdeen When built 1867-3 M^o
 By whom built Scythie Owners Rose & Co
 Port belonging to Aberdeen Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Ratcliff Dry Dock & Afloat
 Last Survey, No. 31317 Port Lon. Classed 11 A
 12.70.

REPAIRS, &c.

Patched the yellow metal sheathing, renewed the main piece of rudder with Co. Oak, fitted eleven pairs of new sides through fastened with yellow metal bolts.

Present Condition of the

Decks <u>Good</u>	Treenails <u>when run good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>Four</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Condition, how ascertained <u>from deck</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Good</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B. 12 LK</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>Good</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>and</u>
Plank (Bottom) and Counter <u>"</u>	Copper <u>2 1/2 M</u> When put on <u>1870</u>	Standing & Running Rigging <u>Sufficient</u>
Engine Room Skylights <u>"</u>	Caulking of <u>"</u>	Hatches <u>Good</u>
Coal Bunker, Openings, Lids, &c. <u>"</u>	Bottom, Deck, & Waterways <u>Good</u>	Scuppers <u>Good</u> Cargo and Main Hatchways <u>Good</u>

General Observations and Opinion,

This vessel is now in good condition and in my opinion eligible to remain as classed.

The Amount of Entry Fee.....£ - : - : is received by me,

Special.....2 : 2 : 15/11/71

Certificate (if required) : :

Committee's Minute 14th November 1871

Character assigned 11 A 1

[Signature]

[Signature]



© 2021

Lloyd's Register Foundation

LOW 654-0155