

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. 487 No. 32161 Survey held at London Date, first Survey Feb. 3rd Last Survey Feb. 20th 1872
 on the Ship "Cormorant" Master A. C. Kennedy
 Tonnage 539 built at Bristol When built 1858
 By whom built Scrutton Sons & Co. Owners Scrutton Sons & Co.
 Port belonging to London Destined Voyage Barbadoes
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock & Afloat
 Last Survey, No. 29656 Port Lon. Classed Cont 65-7A 10 12 68

REPAIRS, &c.

Sighted the bottom, patched the yellow metal sheathing removed the main piece of Studder with C. Oak.

Present Condition of the

Decks <u>Good</u>	Treenails <u>When seen good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats <u>Three</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ritto Ditto at other places	Condition, how ascertained <u>from deck</u>
Planksheers <u>when</u>	Keelsons	Sails <u>Good</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B. 1 S. 2 A.</u>
Topsides	Ceiling	Cables <u>Good</u>
Wales	Rudder	Hawsers and Warps <u>And</u>
Plank (Bottom) and Counter <u>Seen</u>	Copper When put on	Standing & Running Rigging <u>Sufficient</u>
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Fids, &c.	Bottom, Deck, & Waterways <u>Good</u>	
General Observations and Opinion,	Scuppers <u>Good</u> Cargo and Main Hatchways <u>Good</u> Hatches <u>Good</u>	

This vessel is now when seen in good condition and in my opinion eligible to remain as classed

The Amount of Entry Fee.....£ - : - : is received by me,
 Special..... 1 : 1 :
 Certificate (if required)..... : : : *J. Lawrence*

Committee's Minute 29th February 1872

Character assigned Cont 7A

